

Date: June 16th, 2021

RE: 105-1031-BL-00XXX and 105-1092-BL-00XXX

To Whom It May Concern,

Production for the 105-1031-BL-00XXX and 105-1092-BL-00XXX series was moved from China to Taiwan. These USB cables obsolete.

Replacement part numbers will be 105-1031-BL-00XXX-1 and 105-1092-BL-00XXX-1

Please review listed drawing for the *new parts* on our web page.

Best regards,

H. Meyer

www.cnctech.us

7402 W. Detroit Street, Suite 180 Chandler, AZ 85226 www.cnctech.us