

Date: December 9, 2015

PCN- 27522

Product Change Notification

Change Title: CHANGE THE KNURL ON THE COUPLING RING FOR THE SLIM-LINE CONNECTORS..

Product (s) Affected: SL402FX, SL403FX, SL404FX, SL405FX, SL402MX, SL403MX, SL404MX, SL405MX, SL412FX, SL413FX, SL414FX, SL415FX, SL412MX, SL413MX, SL414MX, SL415MX, 2504MX, SL36X, SL37X, P3034 5C3094

Reason for Change: FACILITATE MANUFACTURING PROCESSES. ELIMINATE SLIVERS CREATED BY THE STRAIGHT KNURL.

Description of Change: CHANGE THE STRAIGHT KNURL TO A DIAMOND KNURL.

Estimated Schedule of Change: 3RD QUARTER OF 2015

Customer Acknowledgement Form

(To be filled out by the customer and returned to Switchcraft)

The indicated Customer Notification letter was received and acknowledged by the undersigned authority.

Name: Signature (Electronic Signature is acceptable)	Print
Company:	Location:
Title:	Date:
Please return the signed PCN form to the attention of:	Switchcraft Customer Service Department

jpulliam@switchcraft.com FAX: 773-792-2129