Würth Elektronik eiSos GmbH & Co. KG EMC & Inductive Solutions

$$\label{eq:max-ey} \begin{split} \text{Max-Eyth-Straße 1} & \cdot \text{74638 Waldenburg} \cdot \text{Germany} \\ \text{Tel.} & +49 \, (0) \, 79 \, 42 \, 945 - 0 \cdot \text{Fax} \, +49 \, (0) \, 79 \, 42 \, 945 - 400 \\ \text{eiSos@we-online.de} & \cdot \text{www.we-online.de} \end{split}$$



Product / Process Change Notification (PCN) ☐ Major change ☐ Minor change		
PCN #:	PCN_FePF_20190315	Change Category:
Affected Series:	WE-PF-1280; 7427929xxx	□ Equipment / Location⊠ General Data□ Material
PCN Date:	March 06, 2019	□ Process
Effective Date:	March 15, 2019	□ Product Design□ Shipping / Packaging□ Supplier□ Software
Contact:	Product Management	Data Sheet Change:
Phone:	+49 (0) 7942 - 945 5001	⊠ Yes □ No
Fax:	+49 (0) 7942 - 945 5179	Attachment:
E-Mail:	pcn.eisos@we-online.com	□ Yes ⊠ No

DESCRIPTION AND PURPOSE OF CHANGE:


Because of a database mismatch, Würth Elektronik updates the orientation of the component in the carrier tape.

There will be no change in form, fit, function, quality or reliability of the product but only a correction to the datasheet.

DETAIL OF CHANGE:

The orientation of the component in the carrier tape is different to the drawing in the datasheet. Because of this the datasheet will be updated to have the same orientation like the parts have it in the carrier tape.

The packing drawing in the datasheet will be updated like following:



RELIABILITY / QUALIFICATION SUMMARY:

There will be no change to the product therefore no additional reliability or qualification testing performed.