

PRODUCT DISCONTINUATION

PD-IF-9J9B-16

Business Unit	Product Line Code	Type of Change	Action	Date of issue
IF	CK1	Discontinuation	Notify Distributors and Field	1/13/2016

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Reason for Discontinuation:

End of Lifespan – Newer products are better, and less expensive to manufacture.

Warranty Information:

Stock Status

Can existing stock still be used? Y

Is mixture of stock acceptable? N

Transaction Dates:

Last Buy from Phoenix Contact: 5/31/2016

Last Scheduled Ship from Phoenix Contact: 6/10/2016

PRODUCT DISCONTINUATION

Previous Product	(if applicable)	New Product
 <p data-bbox="332 966 609 997">Figure 1 MCR-PT100-...</p>		 <p data-bbox="917 976 1372 1008">Figure 2 MINI MCR-2-RTD-UI 2902049</p>

Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

Derek Sackett
DSACKETT@PHOENIXCON.COM

Thank you,

Derek Sackett

Derek Sackett, Product Marketing Lead Specialist

PRODUCT DISCONTINUATION

Discontinued Part#	Type Description	Replacement Part#	Type Description
2810311-USA	MCR-PT100-U-DC	2902049	MINI MCR-2-RTD-UI
2810337	MCR-PT100-I-DC	2902049	MINI MCR-2-RTD-UI
2810340-USA	MCR-PT100-U	2902049	MINI MCR-2-RTD-UI
2810353-USA	MCR-PT100-I	2902049	MINI MCR-2-RTD-UI