



# PRODUCT DISCONTINUANCE NOTIFICATION

## PDN0704

---

### Change Description:

*This is an update to PDN0704; please see the revision history table for information specific to this update.*

Altera will be discontinuing the EPCS16SI16N ordering code.

### Reason for Change

The EPCS16SI16N product is being replaced by a smaller package option (8-pin SOIC).

### Key Obsolescence Dates

Date for last order acceptance: March 14, 2010  
Date for last Altera shipments: September 14, 2010

### Products Affected

#### Discontinued Configuration Product Ordering Code

Discontinued Ordering Code	Replacement Ordering Codes*
EPCS16SI16N	EPCS16SI8N (Small board change required)

\* Contact local sales office for other higher-cost solutions requiring no changes to the board layout.

## Contact

For more information on this PDN, please contact Altera Customer Quality support at [customer-quality@altera.com](mailto:customer-quality@altera.com).

---

*In accordance with JESD46-C, this change is deemed acceptable to the customer if no acknowledgement is received within 30 days from this notification.*

---

## Revision History:

Date	Rev	Description
09/13/2007	1.0.0	Initial Release
01/31/2008	1.1.0	Update Replacement Ordering Codes with a Comment