

Product Family	10g Gen,AutolinkII,Battery, BUS BAR,Compact Falsh,Displayport,DVI,HDMI,Header,HSAUTOLINKII,iPass,MicroSD Header,MODULAR JACK,Power Edge,SATA+USB,SD header,SD MEMORY, SD/IO CARD,SIM,Stacked QSFP+,T flash,TFP Header,TFP, USB&ESATA	10692749		
		GCN Number		
Series	10502/10503/10504/10507/10514/10516/10518/15103/15104/15107/15112, etc.73 series totally, detail list provided upon request			
		Date Issued		
Reason For Change	Supplier Change			
Change Description	The purpose if this letter is to inform you that Molex CD resin supplier will change production site from Malaysia &Taiwan to Nantong, China due to supplier strategic consolidate. Affected LCP number is E130I BK205P (MXPN:899920212) and E130I VF2201(MXPN:899920213). There is no risk, and impact on the products spec by this location change . This change only affected Molex ChengDu plant which impact by that supplier.			
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.			
Reason For Short Notice Exception	Not Applicable			
Assessment Of Change (How Product Will Be Qualified & Validated)	We will make qualifciaton plan by this week and estimated finish test by end July			
Internal Molex Qualification Date (Planned Date Information Available)	September 30, 2015			
Sample Availability Date (Changed Part)	October 30, 2015			
Date of Implementation	January 01, 2016			
Method of Identifying Change	start production with new LCP after we use out all old LCP, Will identify change based on production order and Z-lot system.			
Recommended Replacement Parts				
Last Time Buy Date for Obsolete Parts				
Last Time Ship Date for Obsolete Parts				

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com