


1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	007	001	020070010000002316	See list below	Connector	2565 Appliance Inlet C6	n/a
<small>*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)</small>							
List of part numbers affected							
3-104-688		6160.0039		6160.0040		6160.0083	
6160.0100		6163.0015		6163.0020		6163.0021	

2 Type of change

UL upgrade from UL 498 to UL 60320-1.
Marking for UL rating 7A/125V~ updated.

3 Detailed description of change



4 Reason of change

Standards update according to the new UL/CSA 60320-1.

5 Release date

The change takes effect in ww 19/2021 (Date code 2119 or higher on label).

6 Impact of change and recommended action

Form	Yes	Change of rating marking.
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	No	-
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
Data sheet 2565	

Product Change Notification					2565 Change of marking		
owner	creation date	release date	released by	change order no	rev	page	D10-052-457
zeierjo	31.03.2021	31.03.2021	muehlema	2020050	C	1 of 1	