

PRODUCT CHANGE NOTIFICATION

PCN#: COPPER, OUTLETS, SURFACE RACEWAY

ISSUE DATE: 2/13/2019

IMPACTED REGIONS: ☑ NA ☑ EMEA ☑ LATAM ☑ AP

REASON FOR CHANGE: UDISCONTINUATION

OTHER

DESCRIPTION OF CHANGE: (Not Required for discontinuation)

Discontinuation of RJ21 Style Category 5e Cable Assemblies, also known as "25-pair Cable Assemblies", and RJ21 Style Category 5e Panels.

Photos of RJ21 Style Category 5e Cable Assemblies and RJ21 Style Category 5e Panels









Back view of panel

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

Reference Page 2 / Linked PDF

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2019	6	14

^{*}Important: After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)	
UTPCH10SR25Y	N/A	
UTPCH15SR25Y	N/A	
UTPCH20SL25Y	N/A	
UTPCH20SR25Y	N/A	
UTPCH8R25Y	N/A	
UTPCH8SL25Y	N/A	
UTPCH8SR25Y	N/A	
UTPCH1012PP25Y	N/A	
UTPCH10L25Y	N/A	
UTPCH10LR25Y	N/A	
UTPCH10R25Y	N/A	
UTPCH10SL25Y	N/A	
UTPCH1512PP25Y	N/A	
UTPCH15L25Y	N/A	
UTPCH15R25Y	N/A	
UTPCH15SL25Y	N/A	
UTPCH2012PP25Y	N/A	
UTPCH20L25Y	N/A	
UTPCH20LR25Y	N/A	
UTPCH20R25Y	N/A	
UTPCH812PP25Y	N/A	
UTPCH8L25Y	N/A	
UTPCH8LR25Y	N/A	
UTPCH15LR25Y	N/A	
UTPCH612PP25Y	N/A	
UTPCH6L25Y	N/A	
UTPCH6LR25Y	N/A	
UTPCH6R25Y	N/A	
UTPCH6SL25Y	N/A	
UTPCH6SR25Y	N/A	
DP24584TV25Y	N/A	
DP48584TV25Y	N/A	
DP245E88TV25	DP245E88TGY	
DP485E88TV25	DP485E88TGY	
DPA245E88TV25	DPA245E88TGY	
DPA485E88TV25	DPA485E88TGY	