

TDK XIAMEN CO., LTD. 1~19# Lian Sheng Rd., North Industrial District, Jimei, Xiamen, Fujian. (361021) Phone : 086-0592-6150333-576

Branch Office_____

Sales div.Tel:

SPECIFICATION APPROVAL

XL-0911-2321 (00) SPEC. No.

MESSRS : DISTRIBUTION

1

2017/7/12 DATE :

			_
CUSTOMER' S	PRODUCT	NAME	:

		PC44PQ40/40Z-12
ſDK	PRODUCT NAME :	PC44PQ40/40Z-12-NN
	THIS SPECIFICATION IS :	
	□ FULLY APPROVED	
	DENIED	
	□ APPROVED UNDER THE	FOLLOWING CONDITIONS
	SIGNATURE :	DATE :
	NAME (PRINTED) :	
	TITLE :	

MANUFACTURING.	Magnetics Business	s Group	SALES DIV.		
PREPARED BY	CHECKED BY	APPROVED BY	REVIEWED BY	AUTHORIZED BY	
2017 .07. 12	2017 .07. 1 3	XVA			
林火阳	吴聪强	6 7112			12
					\checkmark
		PRÓDUCT	CLASSIFICATION	CODE :	
		7			

Basio	c contents			
1).	Scope of App	lication		
	This specifi delivered to		be applied for the Ferrite cores	to be
2).	Name of proc	luct		
	The name of be defined		b be defined in this specificatio PC44PQ40/40Z-12-NN	n shall
3).	Related Spec	cifications		
4).	Description			
1	I	tems	Attached drawings and tables	Page
	Outer appea	arance		
		e and size		2
	Electrical			
	char	racteristics		2
	Marking			2
	Manufacturi	ing site		2
	Others			3
Revi	sion Records			
Edition	Date	Revised by	Revision	
00	2017/7/12	Huoyang Lin	First Issue	
				1

Ferrite & Magnet Products Business Group Specification No.

XL-0911-2321 (00)

TDK CORPORATION

PAGE 2/3

1. Dimensions (Unit:mm)



2. Electrical characteristics

Item	Specification	Test conditions
		●EQUIP.: LCR METER(Agilent 4284A)
		or equivalent
Inductance	43. 0mH±25%	●FREQ. : 1 kHz
	(at 25°C)	●LEVEL : 0.5 mA
		●COIL : 2-UEW Ø 0.40 N=100 Ts
		●EQUIP.: B-H ANALYZER
		●FREQ. : 100 kHz
Core loss	6.56 W MAX (at 100°C)	●LEVEL : 200 mT
		●COIL : N1=N2=5Ts
		●MEASURE MODE: Z+Z

3 Marking

"PQ4040 Year Month Date PC44 X Z" are marked on the backside of cores.

- 4. The core shall be supplied as pairs.
- 5. Manufacturing site

China:TDK Xiamen Co., Ltd

Specification No.

XL-0911-2321 (00) TDK CORPORATION

Inspection Test Schedule

Magnetics Business Group of TDK CORPORATION performs outgoing inspection tests on the inspection items in Table-1. The inspection shall be performed according to ISO-2859-1 Inspection level I (n=10, c=0 for dimension and n=5, c=0 for core loss)

Table-1. AQL and Inspection items

	AQL	Inspection Items
Α	0.4 %	Inductance and Crack
В	1.0 %	Dimensions
С	1.5 %	Chipping

Permissible limit of chips are prescribed as follows :

- (1) Depth of a permissible chip shall be 1.0 mm max. on mating faces and 1.2 mm max. on other faces. Chips on the corner should be judged by Table-2.
- (2) For the chips more than two on a core piece, the total area of chips shall be used as judgement.
- (3) Others Not described above are based on IEC 60424 specification.

Table-2. Permissible limit of the area of chips.

			Class		
Mating face	6.0	(6.0	mm ²)
Except mating face	12.0	(12.0	mm ²)

Specification No.

XL-0911-2321 (00)

TDK CORPORATION

	CAUTION !
	 CAUTIONS Please seriously consider the following points in order to minimize heat generation: Select the material & shape of ferrite cores by utilizing the publisher nominal and min./max. values of magnetic properties especially; AL-value Saturation Flux Density(maximum) Core Loss Temperature Coefficients Frequency Characteristics Curie Temperature
•	Provide proper insulation of windings by selecting non-corrosive and non-interacting materials and take care to avoid overfill of coilformer and scrapes or abrasions of wire insulation during winding.
•	Insulation is further enhanced by use of a case, bobbin, tape, cement or other appropriate insulating medium with a thermal expansion coefficient very similar to that of ferrite.
•	Avoid excessive force or poor fit of test fixtures and tools to prevent cracking or chipping the ferrite core.
•	Provide clearance between the case, bobbin, coil and core to prevent cracking of the core and insulation breakdown.
•	Distribute the coil windings evenly, preferably with Bi-Filar Windings, to prevent hot spots in the windings which could cause combustion.
•	Keep safety in mind to prevent transient currents and to position the transformer assembly so that any heat generated in normal usage will not damage other circuit components even if another circuit should fail.
	 To prevent personal injury when handling ferrite cores during assembly follow these precautions; Ferrites, a ceramic material, are fragile and can chip and crack when mishandled. Avoid placing ferrite cores near strong magnetic fields. Prevent mechanical shocking of cores when using fixtures or tools. Prevent thermal shocking of cores when may cause cracks. Polished cores have sharp mating edges. Avoid touching these surfaces. Because of the considerable weight of ferrite cores, be extra careful when stacking or handling cartons of cores. Avoid reprocessing ferrite cores. Ferrite cores are not edible. Make sure to keep ferrite cores away from young children so that they do not attempt to eat the cores.