



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000870

DATE: 29-May-2018

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX5116EEE+	N/A			Part reactivated from prior notice: M000847
Lead-Free Conversion	MAX3293AUT	MAX3293AUT+	29-May-2019	28-Nov-2019	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX3293AUT-T	MAX3293AUT+T	29-May-2019	28-Nov-2019	Part is leaded. Request information on lead-free version
Discontinuance	1209002118E	N/A	29-May-2018	29-May-2018	Part can no longer be manufactured
Discontinuance	1209002118K	N/A	29-May-2018	29-May-2018	Part can no longer be manufactured
Discontinuance	DS1099U-FA/V+	N/A	29-May-2018	29-May-2018	The part was not released
Discontinuance	DS1124U-25+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	DS1124U-25+T	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	DS1553W-120+	N/A	29-May-2018	29-May-2018	Part can no longer be manufactured
Discontinuance	DS1553WP-120+	N/A	29-May-2018	29-May-2018	Part can no longer be manufactured
Discontinuance	DS1553WP-150+	N/A	29-May-2018	29-May-2018	Part can no longer be manufactured
Discontinuance	DS17285-3+	DS17285S-3+	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	DS17285-5+	DS17285S-5+	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	DS1802+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	DS1806-050+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	DS1806-100+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	DS1808Z-050+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	DS1808Z-050+T&R	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	DS1809U-050+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	DS32506WFR	N/A	29-May-2018	29-May-2018	The part was not released
Discontinuance	DS3904U-010+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	DS4776P+	N/A	29-May-2018	29-May-2018	Part can no longer be manufactured
Discontinuance	MAX11100EWC+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX11100EWC+T	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX1179EVKIT	N/A	29-May-2018	29-May-2018	EVKIT is No Longer Supported
Discontinuance	MAX1204ACPP+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 29-Jun-2018

Discontinuance	MAX1204AEPP+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX15000AEUB+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX15000AEUB+T	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX1533AETJ+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX17106ETN+	N/A	28-Nov-2018	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX1717EEG+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX20731EVKIT#	N/A	29-May-2018	29-May-2018	EVKIT is No Longer Supported
Discontinuance	MAX20736EPL+	N/A	29-May-2018	29-May-2018	The part was not released
Discontinuance	MAX2119CTI+	N/A	29-May-2018	29-May-2018	The part was not released
Discontinuance	MAX262ACNG+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX263ACPI+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX263BCPI+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX263BEPI+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX264AEPI+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX264BCPI+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX267ACNG+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX2769E/W-GB6	N/A	29-May-2018	29-May-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX3001EEWP+	MAX3001EEUP+	29-May-2018	29-May-2018	Part can no longer be manufactured
Discontinuance	MAX3001EEWP+T	MAX3001EEUP+T	29-May-2018	29-May-2018	Part can no longer be manufactured
Discontinuance	MAX3232EEAE+G1Z	MAX3232EEAE+	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX3243CAI+TG1Z	MAX3243CAI+	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX3314CSA+	MAX3314ESA+	29-May-2018	29-May-2018	The part was not released
Discontinuance	MAX34461ETM+T	MAX34461AA00+T	29-Aug-2018	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX514ACNG+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX514AENG+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX514BCNG+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX5253ACPP+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX527DENG+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX606EVKIT	N/A	29-May-2018	29-May-2018	EVKIT is No Longer Supported
Discontinuance	MAX6380XR41+TG125	MAX6380XR41+T	29-May-2018	29-May-2018	Part can no longer be manufactured
Discontinuance	MAX6470EVKIT	N/A	29-May-2018	29-May-2018	EVKIT is No Longer Supported
Discontinuance	MAX710EVKIT	N/A	29-May-2018	29-May-2018	EVKIT is No Longer Supported
Discontinuance	MAX7360EVKIT+	N/A	29-May-2018	29-May-2018	EVKIT is No Longer Supported
Discontinuance	MAX809REUR+CF1	MAX809REUR+T	29-May-2018	29-May-2018	Part can no longer be manufactured
Discontinuance	MX7537LN+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured
Discontinuance	MX7572LN05+	N/A	29-May-2019	28-Nov-2019	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 29-Jun-2018

Discontinuance	VT1596S76EVKIT#	N/A	29-May-2018	29-May-2018	EVKIT is No Longer Supported
Discontinuance	VT273MFPR	VT273MFPX	29-May-2018	29-May-2018	Part can no longer be manufactured
Discontinuance	VT273SAFQR	VT273SAFQX	29-May-2018	29-May-2018	Part can no longer be manufactured
Discontinuance	VT7505BEVKIT#	N/A	29-May-2018	29-May-2018	EVKIT is No Longer Supported